

6 July 2016

Kerry Deane
5D / 30 Westward Ho Rd
Glen Eden
Auckland
0602

Dear Kerry

Re: Request for information on the wastewater line at 9 Hurdlow Place, Manly

Thank you for your email dated 1 July 2016 in regards to maintenance records for the wastewater line in the property at 9 Hurdlow Pl, Manly.

Attached is the only record relating to the wastewater pipe on the property. This overflow occurred in 2004 prior to Watercare assuming responsibility of the water and wastewater networks following Auckland Council amalgamation, and would have been managed by Rodney District Council. As such this is the only record we have relating to this occurrence.

We have had no further reported overflows at this property since 2004.

Further to your queries about the future of this pipe, at present it is not schedule for removal or replacement. Asbestos Cement (AC) pipes have an estimated life expectancy of 60. According to our records, the wastewater pipe was installed in 1975 and is within this range and is operating as designed. Maintenance of the pipe will be done as required should faults occur.

With regards to your request to remove the pipe, can you please confirm why this is necessary so I can direct you as appropriate.

Yours faithfully,



Leanne McKenzie
Networks Water Quality & Environmental Compliance Analyst
Watercare Services Limited