Attachment A – Consultations on Roading and Parking Changes (October/November 2016)

Business Unit	Location	Description	Date	Comment
Road Safety	Titirangi Rd, Croydon Rd and Parker Ave, New Lynn	Intersection Improvements - Why are the changes required? Drivers turning from Titirangi Road into Croydon Road must give way, but the close proximity of traffic signals causes confusion to drivers and has resulted in a high number of crashes at this intersection in the past five years. The proposed changes will improve the overall safety of the intersection. The Broken Yellow Lines outside No.143 Titirangi Road are required to allow visibility for drivers to see pedestrians and viceversa. A parking space will be reinstated outside No. 147 to minimise the loss of onstreet parking. The Broken Yellow Lines next to the bus stop outside No.151 Titirangi Road are required to allow space for bus drivers to enter and exit the bus stop safely. This will improve efficiency of this service. What are the proposed changes? Relocate the signalised pedestrian crossing from No.143 Titirangi Road to No.145 Titirangi Road. Relocate the 'Keep Clear' limit line to improve visibility for drivers turning right from Titirangi Road into Parker Avenue Install No Stopping At All Times (Broken Yellow Lines) restrictions to allow visibility and accessibility.	14 November 2016	