

**Attachment C:** Encroachments and site photos

**Figure 1:** The applicant's existing gravel accessway over Kanuka Reserve is indicated with a red arrow.



**Figure 2:** The neighbour's driveway at 2 and 4 Kanuka Road is bordered in aqua and the encroachment is indicated with a blue arrow (this is a small triangle encroachment on Kanuka Reserve at 1264 Sandspit Road).



**Figure 3:** Yellow triangle indicates the reserve with the underlying encroachments from 1262 Sandspit Road and 2-4 Kanuka Road



**Figure 4:** Photos of access to the garage on site- 1262 Sandspit Road (the garage is on Kanuka Road as the applicant's site is on the corner of Sandspit Road and Kanuka Road



