

**Attachment B**



Cracks extend close to boundary

Tarpaulin laid by landowner to reduce water ingress

**Figure 2: Photograph of landslide crest, looking west. Private property at 3 Pohutukawa Road on the left of the image.**